



Pedders Suspension Ringwood

Enegine Group Pty Ltd
ABN: 92 131 666 094
59 Bond Street
Ringwood, VIC 3134
Ph. (03) 9873 5122 Fax (03) 9879 2543


Date 15/05/2012 16:25
Page 1 of 3
Job Card No. 000 003 689
Staff

	Before		After

Rim Size

Any component that in our opinion is likely to become unserviceable in 6 months or 10,000kms of the inspection based on our experience of both the vehicle type and model, kms travelled and likely driving situation will be recommended for immediate replacement

Name		
Address		
Phone		Mobile
Email		
VIN Number		Rego Number
Make	Toyota	Model Soarer
Year &/or Code	1991-1998 JZZ / UZZ30,31,32	Model Var JZZ / UZZ 30
Description	Soarer 92	Build Date
Engine Cylinders		Fuel
Transmission	Capacity	Body Type
Colour	Drive Train	Mileage 82212
Accessories		
Customer Instructions	.Suspension & Brake Check and Report HARSH RIDE	



Result	Comment	Part	Qty	Price
FRONT SUSPENSION				
Shocks				
Springs				
Bump Stops				
Strut Mounting Plate				
Lower Ball Joint	Fail	Excessive Movement, Require Replacement	SUBLET	2 \$480.00
Lower Control Arm & Inner Bushes				
Upper Ball Joint				
Upper Control Arm & Inner Bushes				
Radius Rod & Bushes				
Leading Arm & Bushes				
Outer Tie Rod Ends				
Inner Tie Rod Ends				
Idler Arm				
Pitman Arm				
Drag Link				
Sway Bar & Bushes				
Sway Bar Links				
Steering Damper				
Steering Gear				
Power Steering Pump				
Power Steering Lines/Belts/Filter/Oil				
Leaf Spring Bushes & U Bolts				
Panhard Rod				
C.V. Joints				
Engine Mounts				
Tyres				
Other				

Pedders Suspension Ringwood

Enegine Group Pty Ltd
ABN: 92 131 666 094
59 Bond Street
Ringwood, VIC 3134
Ph. (03) 9873 5122 Fax (03) 9879 2543

Date 15/05/2012 16:25
Page 2 of 3
Job Card No. 000 003 689
Staff

Name Alistair
VIN Number 6U900JZZ300018779
Make Toyota
Year &/or Code 1991-1998 JZZ /
UZZ30,31,32
Description Soarer 92
Rego Number
Model Soarer
Model Var JZZ / UZZ 30
Build Date

	Result	Comment	Part	Qty	Price
FRONT BRAKES					
Brake Fluid Condition					
Front Pads	Fail	Near Min Thickness - Recommend Replacement			
Front Rotors					
Front Caliper					
Front Caliper Slides					
Front Shoes					
Front Drums					
Front Wheel Cylinders					
Front Shoe Hardware					
Front Hoses & Lines					
Master Cylinder					
Booster & Vacuum Lines					
ABS Modulator					
Wheel Bearings or Hub Assemblies					
Other - Front					
REAR SUSPENSION					
Shocks			8255	2	\$410.00
Springs	Fail	Below Specified Height, Recommend Replacement	2123	2	\$235.00
Bump Stops	Fail	Perished, Require Replacement	4359	2	\$87.00
Strut Mounting Plates					
Lateral Arms - Upper	Fail	Ball joint excessive play			
Lateral Arms - Lower	Fail	Ball joint excessive play			
Trailing Arms - Upper					
Trailing Arms - Lower					
Toe Arms					
X Member Mounts					
Sway Bar & Bushes					
Sway Bar Links	Fail	Links knocking	4202	2	\$115.00
Panhard Rod					
Leaf Spring Bushes & U Bolts					
C.V. Joints					
Tyres					
Towing Equipment					
Other		Diff bushes starting to split			

Pedders Suspension Ringwood

Enegine Group Pty Ltd
ABN: 92 131 666 094
59 Bond Street
Ringwood, VIC 3134
Ph. (03) 9873 5122 Fax (03) 9879 2543

Date 15/05/2012 16:25
Page 3 of 3
Job Card No. 000 003 689
Staff

Name Alistair
VIN Number 6U900JZZ300018779
Make Toyota
Year &/or Code 1991-1998 JZZ /
UZZ30,31,32
Description Soarer 92
Rego Number
Model Soarer
Model Var JZZ / UZZ 30
Build Date

	Result	Comment	Part	Qty	Price
REAR BRAKES					
Rear Pads	Fail	Near Min Thickness - Recommend Replacement			
Rear Rotors					
Rear Calipers					
Rear Caliper Slides					
Rear Brake Shoes					
Rear Drums					
Rear Wheel Cylinders					
Rear Shoe Hardware					
Rear Hoses & Lines					
Brake Proportioning Valve					
Park Brake					
Wheel Bearings or Hub Assemblies					
Other - Rear					
Road Test					
SERVICE ITEMS					
Suspension Check					
Brake Fluid Flush					
Power Steering Service & Flush					
Wheel Alignment					
Wheel Balance					

Parts	\$967.00
Labour	\$360.00
Total	\$1,327.00

Comments

I, the undersigned hereby authorise the work on my vehicle described above. I authorise Pedders and employees and agents, to drive the motor vehicle for testing purposes, without Pedders, and its employees and agents, incurring any liability except loss or damage caused by gross negligence.

Signature
Date